Tetra Tech Allegations Catalog Draft V1 2017-8-14

Information

Citation

(most

Source Public

Comments

			Information	Citation	(most	Source	Public	Comme	
Tracking number	Type of Fraud	Type of info	Summary	Details	Citation	Source 20	17-7 2016 N 2 11 12	2014 T Pu 13	ıblic - Other 14
:	1 1	1	Scans were supposed to be used to pick soil sample locations, but in late 2008 began sampling 5-10 ft away where scans showed low levels	less likely to be found using K- 40 comparisons	Main text p. 1	: 11	1		
	2 1	2	Took false samples from far away: 1) sewer trench ir front of 500 series bldgs, 2) former theatre building, 1 3) near Bldg 521 under two palm trees	Matched faked	s Main text nn	11	1		
			Smith said soil substitution happened "pretty much every day" over at least the last 1.5 yrs he worked 4 there. Total 800-1,000 false samples	wateried raked	Main text, pp.		1		
	4 1	2	Samples switched at Bldg 517, Bldg 707 Triangle Area in Parcel E, Former 500 series Bldgs in Parcel D, Nort Pier, Shacks 79 and 80, Parcel C		Main text, p. 1	. 11	1		
!	5 1	2	fraudulent practices escalated after contract changed from time-and-materials to firm fixed-price Fraudulent trench soil confirmation sampling was	I	Main Text, p. 1	1 11	1		
	6 1	2	associated with Anthony Smith, Steve Rolfe, Tina 3 Rolfe, Rick Zahensky, Justin Hubbard, Parcel G, Bldg 351A in 2008 "got rid of"		Main text, pp.	11	1		
	7 2	1	contaminated soil sample and chain of custody recor 1 and marked location clean Bldg 3514 disappeared sample Anthony Smith Josh	d	Main text,pp.	11	1		
;	8 2	1	Bldg 351A disappeared sample Anthony Smith, Josh 3 Hooper, Bill Dougherty, Dennis McWade Parcel G, Bldg 351A in 2008 "got rid of"		Main text,pp.	: 11	1		
!	9 2	1	 2 contaminated soil sample 2009 Fisher Ave & Spear 2-3 pCi/g Cs-137 6 inches deep Smith was told to get rid of sample and chain o 	f	Main text,pp.	: 11	1		
1	0 2	2	1 custody Location Fisher & Spear ave. behind wall uphill 6		Main text, pp.	11	1		
1	1 2	2	2 inches deep Disappearing samples Anthony Smith, Jeff Rolfe, Ray		Main text, pp.	11	1		
1	2 2	2	3 Roberson Carey Bell 2009 fencing found to be contaminated but staff told		Main text, pp.	11	1		
1	3 2	3	to hide result and delete data in "Access" computer 1 system Radioactive fencing Susan Andrews, Dennis McWade Phil Poole, Bob Evans, Charles Taylor, Rhonda	,	Main text, p.1	11	1		
1	4 2	3	 3 Richardson, summer 2010 - early 2011 Class 2 and Class 3 scans in buildings and smears "just set your meter down on 	1	Main text, p.1	11	1		
1	5 3	0	1 the ground and let it count.		Main text p. 19	11	1		
1	6 3	0	Fraudulent building scans for nearly all buildings in Hunters Point. Specifically Building, 707, buildings and building footprints throughout the 500 series and buildings 351, 351A, 411,401,414,406, 144,146,130, 2 103, 113, 521, 103, 114, 145, 130, 439, 366, 813	d	Main text p. 1	· 11	1		
			Building Scans Anthony Smith, Steve Rolfe, Jeff Rolfe		·				
1	7 3	0	3 Rick Zahensky, Bill Dougherty, Justin Hubbard When downloading data from Ludlum 2350 changed numbers. Also for Ludlum 2360 (alpha and beta). Zahensky took a computer home to change scan		Main text p. 19	11	1		
1	8 4	0	results overnight. Results were delivered a day late. Data tampering Tina Rolfe, Ray Roberson, Joe		Main text pp.	11	1		
1	9 4	0	Cunningham, Hustin Hubbard, Rick Zahensky, Steve 3 Rolfe, Bert Bowers, Neil Berrett, Phil Smith Early to July 2006 Conveyor belt scanning excavated fill ran too fast and silenced sensor alarms so would not have caught contamination in tens of thousands		Main text pp.	11	1		
2	0 5	1	1 of CY soil Conveyor belt too fast for Parcel E IR-02 and PCB		Main text pp.	11	1		
2	1 5	1	2 removal area Bert Bowers, Ulrika Messer, Neil Hart, Joe Levell,		Main text pp.	11	1		
2.	2 5	1	3 Mike Wilson, Gary Wilson, Jane Taylor Orders were given to take samples "from anywhere" instead of from the proper Radiation Screening Yard		Main text pp.	11	1		
2.	3 5	2	1 (RSY) samples Unqualified workers who did not understand health risks of exposures could have been exposed, swung		Main text p. 28	11	1		
2	4 5	3	1 detectors too high and too fast		Main text pp.	11	1		
2	5 5	2	Radiation Screening Yards Jane Taylor, Arthur Jahr, 3 Samantha Taylor, Kari Guidry, Thorpe Miller		Main text, pp.	11	1		
2	6 5	2	Parcel UC-3 Work Area #16 had 1,023 CY soil removved. 10 CY of soil were remediated as 2 containing radioactive and chemical contamination.		Main text, p. 2	! 11	1		
2	7 5	2	RSY samples collected in locations that intentionally avoided the high radioactivity locations and were allowed to be reused as backfill. 2011 trucks with soil from RSY pads frequently failing		Main text, p. 2	! 11	1		
2	8 6	0	portal monitor screening. Later the sensitivity was 1 reduced	All 37 truckload	s Main text, pp.	11	1		

Need to know

EPA techn TechL Leido EPA

Navy ical aw s Mgmt Not pt Not pt Not pt Sealed Sealed unspecified 1 2 3 4 5 21 22 15 31 32 33

Tetra Tech Allegations - Enforcement Confidential

Read Me

Key:

Type of fraud

- 10 Fake soil sampling
- 11 Fraudulent sampling Stage 1 collected nearby
- 12 Fraudulent sampling Stage 2 collected from far away
- 20 Destruction of "hot" soil samples and their records
- 21 Bldg 351A
- 22 Fisher & Spear Streets
- 23 Radioactive fencing
- 30 Fraudulent Building Surveys
- 40 Fradulent data reporting
- 50 Offsite disposal and backfill
- 51 Conveyor belt too fast
- 52 Potentially contam soil used as backfill
- 53 Unqualified personnel
- 60 Portal Monitor

Type of info

- 1 Patterns and practice
- 2 Locations
- 3 Names of persons associated with falsification
- 4 Timing and frequency

Source (chronological order) Public

- 11 2017 Jun NRC Petition
- 12 2014 Tetra Tech Internal report anomolous soil samples
- 13 2016 Feb NRC Enforcement Action
- 14 Public other

Not Public

- 21 2016 Sep David Anton statement to NRC
- 22 2017 Mar David Anton call and email to Lily Lee and Brianna Fairbanks
- 23 Not public other

Under Seal

- 41 2014 June NRC investigation transcripts
- 42 2016 June Qui Tam transcripts
- 43 Sealed unspecified/other

Need to Know

- 1 Navy Pat Brooks, Matt Slack, Zach Edwards, Thomas Machiarella
- 2 EPA Technical team Lyndsey Nguyen, David Kappelman, John Chesnutt
- 3 EPA Consultants Techlaw Karla Brasaemle, Jana Dawson
- 4 EPA consultants Leidos Donna Getty, Anita Singh
- 5 EPA Management Enrique Manzanilla, Angeles Herrera

Locations

Tracking Type of Type of

number Fraud info Summary Details Citation Source (mc 2017-7 NR 2016 NRC E 2014 Tetra Public - Other

Names

Potentially associated with falsified samples

Tracking Type of Type of

number Fraud info Summary Details Citation Source (mc 2017-7 NR 2016 NRC E 2014 Tetra Public - Other

Tetra Tech Allegations Catalog Draft V1 2017-8-14

		Information			ce (most pı Sc			Source Public			ts	Need to know											
Tracking	Type of	Type of				•					<u></u>		EPA			EPA	•						
number	Fraud	info	Summary	Details	Citation	Source (mo	2017-7 NRC	2016 NR	C [2014]	Tetra Public	: - Other	Navy	technic	cal Techl	aw Leidos	Mgmt	Not p	ublic Not	public Not	public Sea	led 201 Se	aled 201 Sea	led unspecifi
							11	-	12	13	14		1	2	3	4	5	21	22	15	31	32	33
			Scans were supposed to be used to pick soil sample locations,	less likely to be																			
			but in late 2008 began sampling 5-10 ft away where scans	found using K-40																			
-	L	11	1 showed low levels	comparisons	Main text	; 11	1																
			Parcel G, Bldg 351A in 2008 "got rid of" contaminated soil																				
7	7	21	1 sample and chain of custody record and marked location clean		Main text	;,;	1																
			2009 Fisher Ave & Spear 2-3 pCi/g Cs-137 6 inches deep Smith																				
10)	22	1 was told to get rid of sample and chain of custody		Main text	., 11	1																
			2009 fencing found to be contaminated but staff told to hide																				
13	3	23	1 result and delete data in "Access" computer system		Main text	, 11	1																
			summer 2010 - early 2011 Class 2 and Class 3 scans in buildings																				
			and smears "just set your meter down on the ground and let it																				
15	5	30	1 count.		Main text	; 11	1																
			Early to July 2006 Conveyor belt scanning excavated fill ran too																				
			fast and silenced sensor alarms so would not have caught																				
20)	51	1 contamination in tens of thousands of CY soil		Main text	; 11	1																
			2011 trucks with soil from RSY pads frequently failing portal																				
28	3	60	1 monitor screening. Later the sensitivity was reduced	All 37 truckloads fa	ail Main text	, 11	1																

Questions